


Folio
Location LÉVIS
Asset type ATV
Make / Model / Year YAMAHA RAPTOR 700R 2024
VIN 5Y4AML6W9RA300334
Odometer
Number of keys 1

Condition pneus arrières usés, quelques égratignures et taches de rouille.
Engine at start-up Fonctionnel
Restrictions to be able to drive -
Motor (displacement in cc) 700
Transmission Manuelle
Training 2x4
Options -

ENTREPEX assumes no responsibility for any errors, valuation changes, or omissions found in this document. The reports are prepared by the judgment of our appraisers who use a set of inspection guidelines to ensure consistency across assets. The information is provided as a guide and it is the responsibility of the bidder to ensure the accuracy of the information.

Damage Report



Section	Damage level	Types of damage	Details	Photo
Pneu arrière gauche	Major	Usure excessive		

Section	Damage level	Types of damage	Details	Photo
Pneu arrière droite	Major	Usure excessive		
Carrosserie côté gauche	Moderate	Égratignure(s)		  
Carrosserie côté droite	Moderate	Égratignure(s)		   

Section	Damage level	Types of damage	Details	Photo
Console	Minor	Rouille		