



INCOMPLETE VEHICLE MFD BY/
VÉHICULE INCOMPLÉT FABRIQUÉ PAR
ISUZU MOTORS LIMITED
JAPAN/JAPON 01/2024
THIS VEHICLE IS AN INCOMPLETE
VEHICLE/LE VÉHICULE EST UN
VEHICULE INCOMPLÉT.
GVWR/PNBV: 8,845 KG (19,500 LB)
GAWR/PNBE: 3,300 KG (7,275 LB)
(FRONT/AV.) 225/70R19.5F TIRES/PNEU
19.5X6.00 RIMS/JANTE
660KPA(95PSI), COLD TIRE
PRESSURE/PRESSION À FROID
GAWR/PNBE: 6,196 KG (13,660 LB)
(REAR/ARR.) 225/70R19.5F TIRES/PNEU
19.5X6.00 RIMS/JANTE
660KPA(95PSI), COLD TIRE
PRESSURE/PRESSION À FROID
DUAL/DOUBLE
GVWR/PNBV: 11,567KG(25,500LB)
VIN/NIV: **JALE5W169R7310759**
TYPE: TRU/CAM
VEHICLE EMISSION CONTROL INFORMATION
/INFORMATION DE CONTRÔLE DES ÉMISSIONS DE VÉHICULES
THIS VEHICLE COMPLIED WITH U.S. EPA AND CALIFORNIA
REGULATIONS FOR 2023 HEAVY DUTY VEHICLES
/CE VÉHICULE EST CONFORME AUX RÈGLEMENTS
DE L'EPA DES ÉTATS UNIS ET DE LA CALIFORNIE
RELATIFS AUX VÉHICULES UTILITAIRES LOURDS DE 2023.
VEHICLE FAMILY CODE: P22X200C-VLD1
/CODE DE FAMILLE DE VÉHICULES
REGULATORY SUB CATEGORY
/CATÉGORIE DE RÉGLEMENTATION
COMMERCIAL VEHICLES AT OR BELOW
30,000 POUNDS GVWR
/VÉHICULES COMMERCIAUX À 13,600 KG (PNEU)
P22X200C-VLD1 (2023)
EMMISSION CONTROL SYSTEM
/SYSTÈME DE CONTRÔLE DES ÉMISSIONS
ISUZU 755T862880
ISUZU
VEHICLE NUMBER
755T862880
DEALER CODE
AIR DATE
PIN 2-90028-700-0

























IMG_2133.jpeg



























IMG_2131.jpeg







IMG_2162.jpeg





IMG_2160.jpeg




















A close-up photograph of a heavy-duty metal door latch mechanism, likely from a vehicle or industrial equipment. The latch is made of dark, weathered metal and is mounted on a white, slightly textured surface. To the left of the latch, a yellow warning label is partially visible, featuring the word "WARNING" in bold black letters. The label contains several lines of smaller text, including instructions like "DO NOT CLOSE DOOR ON STRAP" and "DO NOT STAND UNDER DOOR WHEN MOVING". A black fabric strap is attached to the right side of the latch mechanism. The entire assembly is positioned above a metal grate floor. A large, semi-transparent "Watermark" is overlaid diagonally across the image.

A close-up photograph of a heavy-duty metal door hinge assembly. The hinge is mounted on a white, possibly painted, metal surface. A yellow warning label is visible on the left side of the hinge, with some text that is partially obscured by a large, diagonal watermark reading "Entirely". The hinge itself is made of dark, weathered metal and shows signs of rust and wear. The background is a white, textured surface, likely the side of a vehicle or a large container. The watermark "Entirely" is written in a large, bold, sans-serif font, slanted diagonally across the image from the bottom left towards the top right.





















IMG_2122.jpeg







IMG_2158.jpeg



IMG_2159.jpeg



