


<b>Folio</b>	051-0400289-001
<b>Location</b>	BOISBRIAND
<b>Asset type</b>	Van tractor
<b>Make / Model / Year</b>	KENWORTH W9 SERIES 900 2019
<b>VIN</b>	1XKWD49X3KR947641
<b>Odometer</b>	1197221 km
<b>Number of keys</b>	1

<b>Declaration</b>	Plusieurs témoins allumés dans le tableau de bord
<b>Condition</b>	Grillage avant brisée, carrosserie égratigné/éclats peintures/rouillé; Un ou plusieurs témoins sont allumés dans le tableau de bord, pare-brise fissuré, aile avant gauche brisée, carrosserie avant tordu
<b>Engine at start-up</b>	Fonctionnel
<b>Restrictions to be able to drive</b>	-
<b>Engine</b>	-
<b>Transmission</b>	Manuelle
<b>Number of reports</b>	-
<b>Options</b>	Couchette, Échappement double
<b>Presence of the notice of compliance Label (SAAQ)</b>	Oui
<b>Notice of Compliance Expiry Date (SAAQ)</b>	2026/10

**ENTREPEX assumes no responsibility for any errors, valuation changes, or omissions found in this document. The reports are prepared by the judgment of our appraisers who use a set of inspection guidelines to ensure consistency across assets. The information is provided as a guide and it is the responsibility of the bidder to ensure the accuracy of the information.**

**Damage Report**









Section	Damage level	Types of damage	Details	Photo
pare-brise-d-fv	Major	Broken, Needs replacement		


Section	Damage level	Types of damage	Details	Photo
calandre	Major	Broken, Dents, Rust		
pc-av-fv	Major	Dents, Rust, Scratch(es)		  
aille-avg-fv	Major	Broken, Paint chip, Scratch(es)		  

Section	Damage level	Types of damage	Details	Photo
ail-avd-fv	Major	Paint chip		
capot-fv	Major	Paint chip		
chass-av-rv	Major	Rust		
porte-d-rv	Major	Scratch(es)		
marches-av-lv	Major	Excessive wear		

Section	Damage level	Types of damage	Details	Photo
body-rv2	Major	Scratch(es)		
reservoir-rv	Major	Rust	fixations rouiller	
chass-mil-rv	Major	Rust		
pc-arr-bv-d	Major	Rust		

Section	Damage level	Types of damage	Details	Photo
aille-arr-av-rv	Major	Scratch(es)		
attelage-bv	Major	Rust		
pc-arr-bv-gm	Major	Rust		
chass-arr-lv	Major	Rust, Scratch(es)		

Section	Damage level	Types of damage	Details	Photo
aille-arr-av-lv	Major	Dents, Scratch(es)		
body-lv	Major	Scratch(es)		
reservoir-lv	Major		fixation rouiller	
exhaust-g-fv	Major	Rust		
portiere-g-lf	Minor	Scratch(es)		

Section	Damage level	Types of damage	Details	Photo
marches-av-rv	Major	Excessive wear		
chass-av-lv	Major	Rust		